HAMBLETON FLOOD ISSUES		Mike O'Flaherty - Resident	20/02/2020
#	Item	Notes	Action
LCC-1	Strengthening Flood	Where and how will the actiosn recomended be monitored	
	Risk Management	and reported on	
	Report Nov 2019		
LCC-2	Register of assets	Does LCC use the list to manage flood risk as required by	
		law	
LCC-3	Section 19 reports	Various actions are recommended what action does LCC	
		take to ensure completion	
LCC-4	Carr Lane "Coppins"	Email sent to Mark O'Donnel requesting detials of work	
	area	proposed yet to start.	
LCC-5	Plans	I request a copy of surface water pipework covering all of	
		Carr Lane	
LCC-6	Carr Lane 3	Gullies blocked / pipes blocked, road flooded gullies still	
	Market St	blocked (beech nuts from trees)	
		(Pam Morgan)	
WBC-1	Planning	WBC planning are capacites existing system considered	
		when new house planning is reviewed.	
WBC-2	Planning	(UU hjas undertaken to supply such information for	
		Hambleton as ALL the sewrage flows through Kiln Lane	
		Pump Station.At what point is planning refused	
WBC-3	Wyre Council Assets	Do Wyre Council have assets they manage that are relevant	
		to Hambleton Flooding	
WBC-4	Culverted Water	The oufall has been opened up, who responsible for	
	Course	ensuring the drain is working (accpeted that is riparian	
		ownership) do the coucil need to send out letter??	
WBC-5	Issues and actions log	This does not accurately represent Hambleton Issues, can	
	DI .	this be corrected	5 11 140/4/00
EA-1	Plans	Plans from EA	Emailed 10/1/20
	Flood Defence Wyma	M/hu has this been halted M/hat is the basis of the delay to	Paul Bond - EA Feedback promised at last
EA-2	Flood Defence Wyre River	Why has this been halted. What is the basis of the delay to Flood Defence Scheme, criteria, factors, does list exist of	forum
	Nivei	proceeding and delayed projects, PB undertook to advise	Torum
		proceeding and delayed projects, FB diluertook to advise	
EA-3	Carr Lane Coppins	Covered ditch adjacent does not flow properly, who is	
	Flooding	repsosible for asking the land owner to clear the water	
	0	course or even remove the pipe to give an open ditch.	
EA-4	Wardelys Creek	Desilting ?	
EA-5	Marsh Lane	Blocked pipe at concrete head wall, blocked pipe at road	
		headwall, outfall desilting	
		(John George Thompson)	
UU-1	Kiln Lane	What level of tide impede the operation of this emergency	
	Pump station		
UU-2	Kiln Lane	Information can a full set of pump station plans be	
	Pump station	available for revue.	
UU-3	Kiln Lane	Does UU considr they should provide a warning of	
	Pump station	potential flooding based on the fact 'their' Kiln Lane System	
	Kilo I o	is inadequate	
UU-4	Kiln Lane	UU advise remodelling and monitors to be placed within	
	Sherbourne	the month	
UU-5	Sherbourne Rd	Existing underground pipework in Sherbourne road was	
		marked on the 2013 drawing s as a query , has anything	
		been done here, has UU mapped it. Manholes are	
		tarmaced over	